## National Transportation Safety Board FACTUAL REPERT AVIATION

NTSB ID: DCA97MA009A Aircraft Registration Number: N87GL

Occurrence Date: 11/19/1996 Most Critical Injury: Fatal

Occurrence Type: Accident Investigated By: NTSB

Location/Time

Nearest City/Place	State	Zip Code	Local Time	Time Zone	
QUINCY	IL	62301	1701	CST	
Airport Proximity: On Airport	Distance From	n Landing Facility:	1	Direction Fro	m Airport: 1

Aircraft Information Summary

Allerant Information Curimary								
Aircraft Manufacturer	Model/Series	Type of Aircraft						
Beech	1900C	Airplane						

Sightseeing Flight: No Air Medical Transport Flight: No

## Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On November 19, 1996, at 1703 CST, a United Express Beechcraft 1900c, Flight 5925 collided with a Beechcraft King Air A90, N1127D, at Quincy Municipal Airport, near Quincy, Illinois. The United Express flight was completing its landing roll on runway 13 and the King Air was departing on runway 4. Both pilots and 10 passengers on the 1900C and both pilots on the A90D were killed. Both aircraft were destroyed. The 1900C was on an IFR flight plan and operating under FAR part 135. The A90 had not filed a flight plan and was operating under FAR part 91. The complete narrative for this investigation is contained in PB97-910404, NTSB/AAR-97/04.

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DCA97MA009A

Occurrence Date: 11/19/1996

AVIATION		Occurrence Type: Accident											
Landing Facility/Approach In	formation												
Airport Name	irport Name Airpor					ion	Run	way Used	Runwa	unway Length		Runv	vay Width
QUINCY MUNICIPAL	QUINCY MUNICIPAL UIN				769 Ft.	MSL	13	13 5398			8 150		
Runway Surface Type: Asphalt													
Runway Surface Condition: Dry													
Type Instrument Approach: NONE	Ē												
VFR Approach/Landing: Straight-	in												
Aircraft Information													
Aircraft Manufacturer  Beech				del/Sei 00C	ries					Serial UC-8	Numbe 37	er	
Airworthiness Certificate(s): Trans	sport									•			
Landing Gear Type: Retractable - Tricycle													
Homebuilt Aircraft? No	Number of Seats:	f Seats: Certified Max Gross Wt. LBS Number							er of En	r of Engines: 2			
Engine Type: Engine Manufacturer: Turbo Prop P&W					acturer:			Model/Series: Rated Power: PT6A-65B 1173 HP					
- Aircraft Inspection Information	- Aircraft Inspection Information												
Type of Last Inspection			Date of L	Date of Last Inspection Time Since La			nce Last Ins	e Last Inspection			ne To	tal Time	
Continuous Airworthiness	Continuous Airworthiness 04/1996 Hours 18446 Hours								446 Hours				
- Emergency Locator Transmitter (	ELT) Information												
ELT Installed?	ELT Operate	ed?				ELT	Aided in	n Locating A	ccident S	Site?			
Owner/Operator Information													
Registered Aircraft Owner			Stree	et Addı	ress								
RAYTHEON AIRCRAFT CRE	DIT ASSN.		City								Stat	е	Zip Code
			Street	t Addr	ess						<u> </u>		
Operator of Aircraft													
GREAT LAKES AVIATION, LTD.  City BLOOINGTON MN							Zip Code 55431						
Operator Does Business As: UNITED EXPRESS AIRLINES  Operator Designator Code: GLBA													
- Type of U.S. Certificate(s) Held:													
Air Carrier Operating Certificate(s)	: Commuter Air Ca	arrier											
Operating Certificate: Operator Certificate:													
Regulation Flight Conducted Under: Part 135: Air Taxi & Commuter													
Type of Flight Operation Conducted: Scheduled; Domestic; Passenger Only													
	]	FACTU	JAL REF	PORT	- AVIATIO	ON							Page 2

National Transportation Safety Board

FACTUAL REPORT

AVIATION

NTSB ID: DCA97MA009A

Occurrence Date: 11/19/1996

AVIATION				Community Transport					$\dashv$				
AVIATION Occurrence Type: Accide													
First Pilot Information													
Name						City				Sta	ate	Date of Birth	Age
On File													30
Sex: F Seat Occupied: Left Principal Profession: Civilian Pilot Certificate Number: On File													
Certificate(s): Airline Transport													
Airplane Rating(s): Multi-engine Land													
Rotorcraft/Glider/LTA:													
Instrument	Rating(s): Airpl	ane											
Instructor R	Rating(s): None	Э											
Type Rating	g/Endorsement fo	or Accident/In	cident Aircra	ft? Yes			С	urrent Bi	ennial Fligl	nt Revie	w? 09/1	996	
Medical Ce	rt.: Class 1	Medica	l Cert. Status	S: Valid Me	dicalno wa	aivers/li	m.		Date o	f Last M	ledical E	xam: 09/1996	
		•							•				
- Flight Tim	e Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Nigh	ght Instrume Actual		nstrument Simula	ment Simulated		Glider	Lighter Than Air
Total Time		4000											
Pilot In Con	nmand(PIC)	2200	700										
Instructor						-				$\rightarrow$			
Last 90 Day	/S	235											
Last 30 Day		91				-							
Last 24 Hou													
Seatbelt Us	sed? Yes	Shou	lder Harness	Used? Yes			Toxico	ology Per	formed? Y	es	Se	cond Pilot? Ye	es
Flight Pla	n/Itinerary												
Type of Flig	ht Plan Filed: IF	R											
Departure F	Point						State	F	irport Iden	Identifier Departur		ture Time	Time Zone
BURLING	TON						IA	BRL			1645		
Destination							State	A	Airport Iden	tifier			
Same as Accident/Incident Location UIN													
Type of Clearance: IFR													
Type of Airspace: Class E													
Weather Information													
Source of Briefing:  No record of briefing													
Method of Briefing:													
FACTUAL REPORT - AVIATION Page 3													

National Transportation Safety Board

FACTUAL REPORT

AVIATION

NTSB ID: DCA97MA009A

Occurrence Date: 11/19/1996

Occurrence Type: Accident

	FIYBOR			Juli elice	, туре.	Accide	;iit							
Weather	Information													
WOF ID	Observation Time	Time Zone	WOF	Elevatio	n	WOF Distance From Accide			dent Site		Direction F	rom Accident S	Site	
UIN	1709	CST		700 Ft. I	MSL_				1 NM De			eg. Mag.		
Sky/Lowes	st Cloud Condition:						Ft.	AGL	Condition of Light: Dusk					
Lowest Ce	iling: Broken		140	00 Ft. <i>F</i>	\GL	Visi	ibility:	12	SM	Altir	meter:	"Hg		
Temperatu	ure: 2 °C [	Dew Point:		3 °C	°C Wind Direction: 70 Density Altitude:							Ft.		
Wind Spee	ed: 9	Gusts:			Weather Condtions at Accident Site: Visual Conditions									
Visibility (F	RVR): Ft.	Visibility	(RVV)		SM	Intens	sity of Preci	pitation:						
Restriction	s to Visibility: None													
Type of Pro	Type of Precipitation: None													
Accident	Information													
Aircraft Da	mage: Destroyed		Aircr	raft Fire	: Grour	nd			Aircraft Exp	olosio	n None			
Classificati	ion: U.S. Registered/U.	.S. Soil												
- Injury Su	mmary Matrix	Fatal	Serious	Minor		None	TOTAL							
First Pi	lot	1					T	1						
Second	d Pilot	1					1	1						
Studen	it Pilot						1	$\neg$						
Flight I	nstructor						1	ヿ						
Check	Pilot				$\top$		1	٦						
Flight E	Engineer				$\top$		1							
Cabin A	Attendants				$\neg$		1	コー						
Other C	Crew				$\neg$		1	٦						
Passen	ngers	10			$\neg$			10						
- TOTAL A	ABOARD -	12						12						
Other 0	3round	0	0		0			0						
- GRANE	O TOTAL -	12	0		0	12								

TRANSP
National Transportation Safety Board
9 3 3 2
FACTUAL REPORT
7 3 2
AVIATION
French

NTSB ID: DCA97MA009A

Occurrence Date: 11/19/1996

Occurrence Type: Accident

1 1 00	
Administrative Information	

Investigator-In-Charge (IIC)

ROBERT P. BENZON

Additional Persons Participating in This Accident/Incident Investigation:

VICTORIA F ANDERSON